

SITE INSPECTION REVIEW FORMSITE NAME: RFL INDUSTRIES, INC.ALIASES: RADIO FREQUENCY LABS; DOWTY RFL INDUSTRIES, INC;SITE I.D.#: NJD 002156677

<u>ITEM</u>	<u>COMPLETE ?</u>	
	<u>YES</u>	<u>NO*</u>
SITE LOCATION (INCLUDING MAP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
SITE BACKGROUND	<input checked="" type="checkbox"/>	<input type="checkbox"/>
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
POTENTIAL FOR DIRECT CONTACT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
CONCLUSIONS + RECOMMENDATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>
REFERENCES	<input checked="" type="checkbox"/>	<input type="checkbox"/>

HRS PRE-SCORE: PRELIMINARY SCORE = 14.3PROJECTED SCORE = 14.7

235666



COMMENTS:

NFRAP. The ground water monitoring pursuant to the certified closure of the unlined percolation lagoon, shows that there are no longer detectable levels of contamination. Ground water drinking targets are also not significant, thus indicating the remote likelihood of a health concern in the vicinity of the site. Present plant operations concern only soldering associated with circuit boards manufacturing. The facility has essentially no history of spills and other related occurrences.

Ground water concerns are being addressed by NJDEP/DWR/Bureau of Ground Water Pollution Abatement.

REVIEWED BY: LARRY TANNENBAUM

DATE: MAY 3, 1990

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS